FREEGOLD RECOVERY INC.

42A01NE0159 2.9714 TECK

010

REPORT ON OVERBURDEN DRILLING

During July 1986 Freegold Recovery Inc. carried out an overburden drilling program on claims L-927910 and L-927911 in Teck Township, Larder Lake Mining Division, Ontario.

Mr. Kelly Dolphin, a Freegold director supervised the program which drilled 14 overburden holes using a Wink "Vibra-Core" drill which are outlined on the attached map. Access to the site was by a rented Suzuki 4 wheel vehicle pulling a trailer with all the gear.

Drill holes varied from 8 feet to 34 feet. All holes were drilled through tailings to get to bedrock below. Five holes were drilled on line 1, one on line 2, three on line 3, two on line 4, and one each on lines 5,6 and 7. The results of the program were inconclusive and more work is recommended.

A breakdown of the expenditures is included for referral.

Kelly Dolphin

FREEGOLD RECOVERY INC.

September 1986

RECEIVED


JAN 22 1987

MINING LANDS SECTION



Bad Rock airstrip






FREEGOLD RECOVERY INC.

SKETCH MAP OF OVERBURDEN DRILLING

TECK TOWNSHIP
LARDER LAKE MINING DIVISION
SCALE : 1" = 200'
BY: KELLY DOLPHIN
SEPT./86



KELLY DOLPHIN

FREEGOLD

RECEIVED
APR 22 1987
MINING LANDS SECTION

FreeGold Recovery Inc.
1555 West 8th Ave.
Vancouver, B.C. V6H 3W4
604-736-5400
Tlx: 04-55482
Qunitle Place, Suite 4040
10145 - 99th Street
Edmonton, Alberta T5J 3H1

DRILL DESCRIPTION AND PROCEDURE


A Vi-Core Sonic Drill was obtained to drill through the tailing for bed-rock chip sample.

The Vibra-Core drill is an acoustic drill producting high frequency sonic vibrations at a rate of approximately 12,000 vibrations per minute. These vibrations are transmitted down the drill stem to produce a resadent motion down the drill. Penetration rates through sand and gravel formations of up to 1 foot per 2 seconds are common.

A 4" casing was driven through the tailing with the sonic head driven by a 7 H.P. Honda gas powered motor. A Flex Cable is used in connecting the head to the power pack, drill casing was broken into 5 foot lenghts, this made the handling of the drill cores easier on the drill operators. The sonic head vibrated the drill casing to the bottom of the tailing. The driving shoe would then vibrate on bed rock causing bed-rock chips to be pulled into the core retainer. A 12,000 lb. winch was then used to pull up the casing.

Drill cores were removed and placed in split 6" PVC pipe used as core boxes. Drill cores were then sampled every 4" using a 5/8" circular tube. All bed-rock chip samples were collected from core material and retained for future analysis.

DRILL LOCATION



Campbell Red Lake Mines Ltd.

Date 7-[illegible]

Hole No. L 1 [illegible]

Sample № 1001

From [illegible] To [illegible]

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date [illegible]

Hole No. L 1 H1

Sample № 1002

From [illegible] To 8'

5' [illegible]

6' [illegible]

7' water

5' [illegible]

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date [illegible]

Hole No. L 1 H1

Sample № 1003

From [illegible] To 13

[illegible] soapy

coarse

5' [illegible]

[illegible]

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date [illegible]

Hole No. L 1 H2

Sample № 1004

From 0 To [illegible]

[illegible]

[illegible]

NORTHERN MINER PRE

Campbell Red Lake Mines Ltd.

Date 7-[illegible]

Hole No. L 1 H2

Sample № 1005

From 6 To 11

2½ water

Dark [illegible]

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-14

Hole No. L 1 H2

Sample № 1006

From [illegible] To 16'

Hard rock

Lost 1 Soapy

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-14

Hole No. L 1 H2

Sample № 1007

From 16 To 24'

1st 3' @ very 9"

water,

grainy

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-14

Hole No. L 1 H2

Sample № 1008

From 24 To 26'

Mixed core

grainy Dark

NORTHERN MINER PRESS - L839

OVERBURDEN DESCRIPTION

Campbell Red Lake Mines Ltd.

Date 7-14-6..

Hole No. L1 H2

Sample № 1009

From ... To 5

1 ... 5'

1½ ... ...

... ...

... ...

... ...

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-14

Hole No. L1 H2

Sample № 1010

From ... To 10

... color

... ...

1st 1 ...

... ...

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date ...

Hole No. ...

Sample № 1011

From 5 To 8

Brown

...

... ...

... ...

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date ...

Hole No. ...

Sample № 1012

From ... To 5

... ...

... ...

... ...

core

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-14

Hole No. L1 H4

Sample № 1013

From 9 To 13

3½' core

5" ... ...

... ...

... ...

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date ...

Hole No. ...

Sample № 1014

From ... To ...

... ...

... ...

... 90 ...

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date ...

Hole No. ...

Sample № 1015

From 0 To 3' ½

1st 1' Brown in

color

... 5' in

decomposed

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-14

Hole No. L1 ...

Sample № 1016

From ½' To 6½'

5' decomp.

... ...

... core

... by ...

... ...

... ...

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-15-56

Hole No. L-2 U-1

Sample № 1017

From 0 To 3'

3' core, 1' overburden

core has been split

Upper half taken

last 1' core

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-15-56

Hole No. L-2 U-1

Sample № 1018

From 3' To 5'

core has been split

Lower half

Lower half

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-15-56

Hole No. L-2 U-1

Sample № 1019

From 8' To 13'

Slimy but

Core recovered

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-15-56

Hole No. L-2 U-2

Sample № 1020

From 0 To 6

Lost core

1st 1' overburden

with N 70° in

next 5' grey

Col sup ch.

min bands, lay

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-15-56

Hole No. L-6 U-1

92.7910 92.7911

Sample № 1021

From 0 To 5'

top 1½ broken

basic Sli.

Core to 3'

and 1'

clay fault

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-15-56

Hole No. L-7 U-1

Sample № 1022

From 0 To 5

20' from collar

Lot Sup. Sc

very light

brown core

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No. L-4 U-1

Sample № 1023

From 0 To 6

Dark green fine

to fine first 2'

Normal with

N20°

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No. L-4 U-2

Sample № 1024

From 0 To 6

[illegible]

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L4 H2

Sample № 1025

From ____ To 1'

top 1' coarse
- 0 clay
1" asbestic core

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L3 H1

Sample № 1026

From 0 To 3

Lost ground
H2O end of
core

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L3 H1

Sample № 1027

From 3 To 8

H2O running
5" of core

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L3 H1

Sample № 1028

From 8 To 13

Lost
clay
core

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L3 H2

Sample № 1029

From 0 To 2

No
return 2'
clay
coarse bad 1'

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L3 H2

Sample № 1030

From 3 To 6

3 of H2O
in core

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L3 H2

Sample № 1031

From 6 To 11

core soupy
no recovery

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No L3 H2

Sample № 1032

From 11 To 16

black mud
in core
lost
core
H2O rising
H2O 4 in of 3'
soupy

NORTHERN MINER PRESS - L839

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No. L3 42

Sample № 1033

From 16 To 21

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-16

Hole No.

Sample № 1034

From 21 To

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date

Hole No. L3 43

Sample № 1035

From 1 To

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-17-66

Hole No.

Sample № 1036

From 6 To 11

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-17-66

Hole No.

Sample № 1037

From 1 To 16

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-17-66

Hole No.

Sample № 1038

From 2 To

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date

Hole No. L3 44

Sample № 1039

From 21 To 26

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date 7-18

Hole No. L3 44

Sample № 1040

From 0 To 4

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date

Hole No.

Sample № 1041

From To

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date

Hole No.

Sample № 1042

From 9 To 14

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date

Hole No.

Sample № 1043

From To

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date

Hole No.

Sample № 1044

From 19 To 24

NORTHERN MINER PRESS - L639

Campbell Red Lake Mines Ltd.

Date

Hole No.

Sample № 1045

From To

NORTHERN MINER PRESS - L639

SWASTIKA LABORATORIES LIMITED

P.O. BOX 10, SWASTIKA, ONTARIO P0K 1T0
TELEPHONE: (705) 642-3244
ANALYTICAL CHEMISTS • ASSAYERS • CONSULTANTS

Certificate of Analysis

ASSAY & DRILL LOGS

Certificate No. 63645 Date: July 17th, 1986

Received July 14th, 1986 16 Samples of tailings

Submitted by FreeGold Recovery Inc., Vancouver, B.C.

SAMPLE NO.	GOLD Oz/ton
1001	0.010
1002	0.024/0.022
1003	0.015
1004	0.015
1005	0.014
1006	0.023
1007	0.018
1008	0.016
1009	0.013
1010	0.019
1011	0.016
1012	0.017
1013	0.018
1014	0.012
1015	0.022
1016	0.024/0.028

Per G. Lebel - Manager

Member Canadian Testing Association

ESTABLISHED 1928

FREEGOLD-CAMPBELL TAILINGS RECOVERY TEST. JUNE, 1986

LINE #	HOLE #	TOTAL (D) DRILL L.	TOTAL (C) COMP. L.	RATIO C/D	SAMPLE #	SAMPLED L.	ASSAY	
2	1	7'	5'	.764				
		8	3	.764	1017	2.29 FT	.016	
		5	8	.764	1018	3.82 FT	.014	.015
		3	13	.764	1019	3.82 FT	.016	
L5	H2	11'8"	9½	.805				
		6	6	.805	1020	4.83 FT	.015	.015
6	H1	9'15"	7'4"	.913	1021	6.75 FT	.019	.019
7	H11	9'10	7'2"	.888	1022	6.39 FT	.014	.014

FREEGOLD-CAMPBELL TAILINGS RECOVERY TEST. JUNE, 1986

LINE #	HOLE #	TOTAL (D) DRILL L.	TOTAL (C) COMP. L.	RATIO C/D	SAMPLE #	SAMPLED L.	ASSAY	
4		11'3"	7'	.672				
		0	6	.672	1023	4.03 FT	.016	.016
4		14'9"	10'0"	.891				
		5'	6	.891	1024	5.34 FT	.020	.018
		6	11	.891	1025	4.45 FT	.017	
3	1	16'	14'	.875				
		0	3	.875	1026	2.62 FT	.017	
		3	8	.875	1027	4.37 FT	.017	.016
		8	13	.875	1028	4.37 FT	.014	
3	2	34'	29'	.852				
		0	4	.852	1029	3.4 FT	.019	
		4	9	.852	1030	4.26 FT	.014	
		9	14	.852	1031	4.26 FT.	.022	.018
		14	19	.852	1032	4.26 FT	.018	
		19	24	.852	1033	4.26 FT	.021	
		24	29	.852	1034	4.26 FT	.015	

FREEGOLD-CAMPBELL TAILINGS RECOVERY TEST. JUNE, 1986

LINE #	HOLE #	TOTAL (D) DRILL L.	TOTAL (C) COMP. L.	RATIO C/D	SAMPLE #	SAMPLED L.	ASSAY	
3	3	35'		.790				
		0	5	.790	1035	4.74 FT	.018	
		5	10	.790	1036	3.95 FT	.022	
		10	15	.790	1037	3.95 FT	.017	.018
		15	20	.790	1038	3.95 FT	.017	
		20	25	.790	1039	3.95 FT	.019	
#1 upper	1	30	29'	.966				
		0	4	.966	1040	3.86	.017	
		4	9	.966	1041	4.83	.018	
		9	14	.966	1042	4.83	.024	.023
		14	19	.966	1043	4.83	.020	
		19	24	.966	1044	4.83	.029	
		24	29	.966	1045	4.83	.030	

FREEGOLD-CAMPBELL TAILINGS RECOVERY TEST. JUNE, 1986

LINE #	HOLE #	TOTAL (D) DRILL L.	TOTAL (C) COMP. L.	RATIO C/D	SAMPLE #	SAMPLED L.	ASSAY
9279							
1	1	16'	14'	.875			
		0	3	.875	1001	2.6 FT.	.010
		3	8	.875	1002	4.3 FT	.024
		8	12	.875	1003	4.3 FT	.015
	2	09	27 1/2"	.948			
		0	6	.984	1004	5.9 FT	.015
		6	11	.984	1005	4.9 FT	.014
		11	16	.984	1006	4.9 FT	.023
		16	20	.984	1007	4.9 FT	.015
		21	26	.984	1008	4.9 FT	.016
1	3	15	14	.933			
		0	5	.933	1009	4.6 FT	.017
		5	10	.933	1010	4.6 FT	.019
1	4	14' 4"	17' 9"	.922			
		0	3	.922	1011	2.7 FT.	.016
		3	8	.922	1012	4.6 FT	.017
		8	13	.922	1013	4.6 FT	.018
		13	18	.922	1014	4.6 FT	.017
1	5	11 1/2	9'				
		0	3 1/2	.791	1015	2.76 FT	.022
		3 1/2	8 1/2	.791	1016	3.9 FT.	.024

Ontario and Mines

(Geophysical, Geological, Geochemical and Expenditures)

W8708.7

Mini

42A01NE0159 2.9714 TECK

900

Type of Survey(s)

OVERBURDEN DRILLING

Claim Holder(s)

FREE GOLD RECOVERY INC. T4665

Address

1333 WEST 8TH AVENUE VANCOUVER B.C. V6H 3W4

Survey Company

SELF

Date of Survey (from & to)

Day	Mo.	Yr.	Day	Mo.	Yr.
06	07	86	20	07	86

Total Miles of line Cut

—

Name and Address of Author (of Geo-Technical report)

KELLY DOLPHIN - 1333 WEST 8TH AVE. VANCOUVER B.C. V6H 3W4

Credits Requested per Each Claim in Columns at right

Special Provisions		Days per Claim
For first survey: Enter 40 days. (This includes line cutting)	Geophysical	
	- Electromagnetic	
	- Magnetometer	
For each additional survey: using the same grid: Enter 20 days (for each)	- Radiometric	
	- Other	
	Geological	
	Geochemical	

Man Days		Days per Claim
Complete reverse side and enter total(s) here	Geophysical	
	- Electromagnetic	
	- Magnetometer	
	- Radiometric	
	- Other	
	Geological	
	Geochemical	

Airborne Credits		Days per Claim
Note: Special provisions credits do not apply to Airborne Surveys.	Electromagnetic	
	Magnetometer	
	Radiometric	

Mining Claims Traversed (List in numerical sequence)

Mining Claim Prefix	Mining Claim Number	Expend. Days Cr.
L	858903	60
	858932	60
	858933	60
	858934	60
	927910	60
	927911	60
	927912	60
	927913	60

RECEIVED

JAN 12 1987

3:25 p.m.

MINING LANDS SECTION

Total number of mining claims covered by this report of work. 8

Expenditures (excludes power stripping)

Type of Work Performed

OVERBURDEN DRILLING

Performed on Claim(s)

L-927910, L-927911

Calculation of Expenditure Days Credits

Total Expenditures			=	Total Days Credits
$19,136.50	÷	15	=	1275

Instructions

Total Days Credits may be apportioned at the claim holder's choice. Enter number of days credits per claim selected in columns at right.

For Office Use Only

Total Days Cr. Recorded	Date Recorded	Mining Recorder
480	JAN 12 1987	Acting
	Date Approved as Recorded 87.4.28	Branch Director

Date	Recorded Holder or Agent (Signature)
JAN. 12/87	Carl P. Forbes

Certification Verifying Report of Work

I hereby certify that I have a personal and intimate knowledge of the facts set forth in the Report of Work annexed hereto, having performed the work or witnessed same during and/or after its completion and the annexed report is true.

Name and Postal Address of Person Certifying

CARL P. FORBES 33 PREMIER AVE. WEST

KIRKLAND LAKE ONT. P2N 2S7

Date Certified	Certified by (Signature)
JAN. 12/87	Carl P. Forbes

1362 (85/9)

2.9714

Bernhardt Twp. M.327

Grenfell Twp. M.351

Otto Twp. M.379

Lebel Twp. M.359

KIRKLAND LAKE

THE TOWNSHIP OF TECK

DISTRICT OF TIMISKAMING

LARDER LAKE MINING DIVISION

SCALE: 1-INCH = 20 CHAINS

DISPOSITION OF CROWN LANDS

PATENT, SURFACE AND MINING RIGHTS
" , SURFACE RIGHTS ONLY
" , MINING RIGHTS ONLY
LEASE, SURFACE AND MINING RIGHTS
" , SURFACE RIGHTS ONLY
" , MINING RIGHTS ONLY
LICENCE OF OCCUPATION
ROADS
IMPROVED ROADS
KING'S HIGHWAYS
RAILWAYS
POWER LINES
MARSH OR MUSKEG
MINES
CANCELLED

NOTES

400' surface rights reservation along the shores of all lakes and rivers.

Areas shown thus ⟨ ⟩ for slime disposal.

Mining claim L.5779 — Mining Rights subject to Sec. 36 of the Mining Act. (R.S.O. 1950).

AREAS WITHDRAWN FROM STAKING

S.R. — SURFACE RIGHTS SECTION	ORDER No.	DATE	DISPOSITION	M.R. — MINING RIGHTS FILE
(S) 43(R.S.O. 1970)	M 76/80	2/1/80	R.S.	171160
(S) 36(R.S.O. 1980)	M 208/82	12/2/82	S.R. & M.R.	15478
(S) 36/80	208/82	2/2/83	3 yrs	
Mineral rights withdrawn from prospecting staking and sale pursuant to [illegible] Reserved MRO 10184 Sept 2/1983				
(Ks) Sec 36/80	M 9/80	2/4/1986	mos	
(Ks) Sec 36/80	M 11/80	2/4/1986	mos	

DATE OF ISSUE
MAR 20 1987
LARDER LAKE MINING RECORDER'S OFFICE

PLAN NO.-M. 392

ONTARIO
MINISTRY OF NATURAL RESOURCES

42A01NE0159 2.9714 TECK

200